


HOW TO: Basic Soldering Techniques for Kit Building




1. Assemble the proper tools.



2. Mount component by bending leads out slightly.



3. Heat iron. Clean tip with damp sponge.



4. Apply heat. Apply solder.



5. Remove solder. Remove iron.



6. Inspect solder. Cut lead.